NexzaPrime

Platinum Plan: example

How your report is laid out, section by section.

Plan	**Platinum Plan**
Price	$110 USD or C$155 CAD, one-off
Reports included	10 detailed reports. The first is run on the VIN given at checkout; the others when you email us each VIN
Delivery	PDF by email within 30 minutes of payment or of adding a VIN

Vehicle: 2003 Honda Accord EX-V6, VIN 1HGCM82633A004352. Specification and recall data are real NHTSA records; history entries marked "illustrative" show the layout only.

NexzaPrime VIN 1HGCM82633A004352

2003 Honda Accord EX-V6

Coupe, Premium Report example

Built in Marysville, Ohio, USA

Summary

Title brands	None reported
Insurance total loss	None reported
Junk or salvage records	None reported
Reported accidents	1 report
Odometer	No rollback found
Manufacturer recall campaigns	13 for this model

Summary lines for title, total loss, salvage, accidents and odometer are illustrative. Recall and specification data below is real NHTSA data for this VIN.

Vehicle specification

Year, make, model	2003 Honda Accord
Trim	EX-V6
Body	Coupe, 2 doors
Engine	3.0 L V6 (J30A4), SOHC, 240 hp, gasoline
Transmission	5-speed automatic
Gross vehicle weight class	Class 1C: 4,001 to 5,000 lb
Manufacturer	American Honda Motor Co., Inc.
Assembly plant	Marysville, Ohio, United States
Front air bags	Driver and passenger
Side air bags	Front row
Curtain air bags	Front and rear rows
Seat belts	Manual, rear center position belt

Title history

Jan 2003, Ohio	First title, new vehicle
Jul 2009, Ohio	Title transfer
Sep 2016, Ontario	Imported and registered in Canada

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

Title brand checks

Salvage	Not reported
Rebuilt or reconstructed	Not reported
Flood or water damage	Not reported
Fire damage	Not reported
Hail damage	Not reported
Junk or dismantled	Not reported
Lemon or manufacturer buyback	Not reported
Odometer not actual	Not reported
Former rental, taxi or police	Not reported

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

Accidents and damage

May 2011, Ohio. Police-reported collision, front impact, vehicle driven from scene. No total-loss declaration followed.

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

Odometer readings

Jan 2003	12 mi, new vehicle
Jul 2009	84,300 mi, title transfer
Sep 2016	148,900 mi (239,600 km), import inspection
Oct 2021	191,200 mi (307,700 km), sale listing

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

Manufacturer safety recalls for this model

Campaign	Issued	Component	Problem and free fix
19V-182	Mar 2019	Air bags: driver inflator	Driver air bag inflator may explode in a crash, sending metal fragments into the cabin. **Dealer replaces the driver air bag inflator, free.**
19V-499	Jun 2019	Air bags: driver inflator	Inflator propellant can degrade after long exposure to heat and humidity and rupture on deployment. **Dealer replaces the driver frontal inflator, free.**
19V-501	Jun 2019	Air bags: passenger inflator	Passenger inflator propellant can degrade and rupture on deployment. **Dealer replaces the passenger frontal inflator, free.**
18V-268	Apr 2018	Air bags: passenger module	A replacement passenger air bag may have been installed incorrectly. **Dealer inspects and replaces the module if needed, free.**
17V-220	Mar 2017	Air bags: passenger module	Replacement passenger air bag modules on some 2003 Accord coupes may contain a Takata inflator. **Dealer replaces any Takata inflator, free.**
15V-370	Jun 2015	Air bags: passenger inflator	Passenger inflator exposed to moisture may rupture on deployment. **Dealer replaces the passenger inflator, free.**
15V-320	May 2015	Air bags: driver inflator	Driver inflator may rupture over time due to moisture intrusion. **Dealer replaces the driver inflator, free.**
14V-700	Nov 2014	Air bags	Passenger inflator in vehicles from high-humidity regions may rupture. **Dealer replaces the passenger inflator, free.**
14V-353	Jun 2014	Air bags	Regional recall for vehicles first sold or registered in California. **Honda replaces the inflator, free.**
12V-222	May 2012	Power steering hose	Hose may deteriorate and leak fluid onto the hot catalytic converter, with a fire risk. **Dealer fits a heat-resistant hose, free.**

Campaign	Issued	Component	Problem and free fix
10V-364	Aug 2010	Ignition interlock	Key can be removed when not in Park, so the vehicle may roll away. **Dealer replaces the interlock pin and lever, free.**
08V-169	Apr 2008	Windshield wiper motor	Water can corrode the wiper motor and stop the wipers. **Dealer inspects, fits a cover or replaces the motor, free.**
04V-176	Apr 2004	Automatic transmission	Heat build-up can chip second-gear teeth and lock the transmission. **Dealer revises the oil cooler line or replaces the transmission, free.**

Real NHTSA recall campaigns for the 2003 Honda Accord. Whether a repair has been done on a particular car is confirmed by a Honda dealer from the VIN, at no charge.

Online listing history

Oct 2021, Toronto, ON	Listed for sale, asking C$3,900

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

Ownership costs and ratings

EPA fuel economy (original)	19 city / 27 highway mpg
Original warranty	3 yr / 36,000 mi basic, 5 yr / 60,000 mi powertrain, both expired

Illustrative entries, to show the layout. In your report this section lists the records found for your vehicle.

NexzaPrime (nexzaprime.com) is operated by Vara Lakshmi LLC. A history report shows reported records only and is not a mechanical inspection or marine survey.